

## 220-1101 Dumps

### CompTIA A+ Certification Exam: Core 1

<https://www.certleader.com/220-1101-dumps.html>



**NEW QUESTION 1**

A technician needs to fix a Cat 5 cable issue. The cable, which is connected to a network jack, fails when it is moved around. Which of the following items must the technician use to fix the issue? (Select TWO).

- A. Scissors
- B. Network tap
- C. Magnetized screwdriver
- D. Tone generator
- E. RJ45 connector
- F. Crimper

**Answer:** AE

**NEW QUESTION 2**

Upon booting a workstation, a technician hears a distinct clicking sound after power is applied to the motherboard. Which of the following would MOST likely be the cause?

- A. RAID
- B. SSD
- C. S.M.A.R.T
- D. HDD

**Answer:** D

**Explanation:**

The clicking sound is the sound of a damaged disk in the HDD

**NEW QUESTION 3**

A user's computer is not receiving a network connection. The technician confirms that the connection seems to be down and looks for the user's port on the patch panel. The port and patch panel are not labeled. Which of the following network tools should the technician use to identify the port?

- A. Network tap
- B. Punchdown tool
- C. Toner probe
- D. Crimper

**Answer:** C

**Explanation:**

Toner Probe Many cable testers also incorporate the function of a toner probe, which is used to identify a cable from within a bundle. This may be necessary when the cables have not been labeled properly. The tone generator is connected to the cable using an RJ45 jack and applies a continuous audio signal on the cable. The probe is used to detect the signal and follow the cable over ceilings and through ducts or identify it from within the rest of the bundle.

**NEW QUESTION 4**

A technician powers on a PC and its monitor and sees the following error message: No input signal detected  
The display lights on the computer are on. Which of the following is a possible solution?

- A. Changing the BIOS settings
- B. Changing the connector setting on the monitor
- C. Checking the power plug on the monitor
- D. Checking the power plug on the PC

**Answer:** B

**NEW QUESTION 5**

A technician needs to add storage to a workstation. The workstation does not have room to add any internal storage, so the technician plans to add an external storage device. Which of the following connection types should the technician MOST likely use?

- A. SCSI
- B. eSATA
- C. PCIe
- D. NVMe

**Answer:** B

**NEW QUESTION 6**

A user reboots a machine. On rebooting, the user hears one beep, and then an error message is displayed. Which of the following are MOST likely causing this issue? (Select TWO).

- A. RAM module
- B. Graphics card
- C. CPU
- D. Boot order
- E. USB flash drive
- F. Power supply

**Answer:** DE

**NEW QUESTION 7**

An IT manager is requesting that the company buy new cables to be used with F-type connectors that are already in house. Which of the following cables should the company buy?

- A. Coaxial out
- B. Plenum
- C. Cat 5e
- D. Fiber

**Answer:** A

**NEW QUESTION 8**

Which of the following network types would be used in a server room to connect virtual servers to high-speed storage?

- A. WAN
- B. PAN
- C. MAN
- D. SAN

**Answer:** D

**NEW QUESTION 9**

A technician needs to improve a workstation's overall response time for frequently used applications and data without removing the current hard drive. Which of the following storage devices should the technician install to BEST accomplish the objective?

- A. M.2
- B. SAS
- C. HDD
- D. SCSI

**Answer:** A

**NEW QUESTION 10**

A technician is commissioning a workstation that is required to have mirrored storage, utilizing two 4TB drives that support one failure. Which of the following BEST meets these requirements?

- A. RAID 0
- B. RAID 1
- C. RAID 5
- D. RAID 10

**Answer:** B

**NEW QUESTION 10**

An insurance company wants to implement cloud computing and would like a cloud solution in which the infrastructure is shared with businesses in the same industry. Which of the following cloud models BEST addresses the company's need?

- A. Community
- B. Private
- C. Public
- D. Hybrid

**Answer:** D

**Explanation:**

In a hybrid cloud model, the infrastructure is shared between public cloud services and an on-premise private cloud. This means that the insurance company can benefit from the scalability and cost-effectiveness of public cloud services, while also having the control and security of a private cloud. This allows the company to access resources that are specialized to their industry, while also ensuring that their data and infrastructure are kept secure.

**NEW QUESTION 15**

Which of the following connectors can be plugged into a Thunderbolt 3 port on a laptop?

- A. miniUSB
- B. microUSB
- C. USB-A
- D. USB-C

**Answer:** C

**Explanation:**

Thunderbolt 3 is a USB-C port, so any device with a USB-C connector can be plugged into it. MiniUSB, microUSB and USB-A are not compatible with Thunderbolt 3.

**NEW QUESTION 20**

A salesperson is using a weather application on a mobile device. The application appears to be draining the device's battery very quickly. Which of the following is the BEST action for the salesperson to take in order to view weather forecasts while travelling?

- A. Enable the GPS service to ensure accurate location detection.
- B. Manually enter office locations in the weather application.
- C. Configure less frequent location checks using cellular location services.
- D. Use the offices' Wi-Fi IP addresses as the geolocation mechanism.

**Answer:** B

**Explanation:**

<https://nerdschalk.com/how-to-fix-weather-app-battery-drain-on-ios-16/>

**NEW QUESTION 21**

A technician is receiving reports that the entire office sporadically loses network connectivity throughout the day. The technician determines the root cause to be EMI. Which of the cable mediums would be the MOST cost effective without sacrificing system performance?

- A. Coaxial
- B. Shielded Cat 6
- C. Plenum Cat 5e
- D. Multimode fiber

**Answer:** B

**Explanation:**

Electromagnetic interference (EMI) is unwanted noise or interference in an electrical path or circuit caused by an outside source. Hence shielded Cat 6 is better

**NEW QUESTION 23**

An organization has some computers running macOS and some computers running Windows. The computers running macOS also need to run a piece of software that is only available on Windows. Which of the following BEST describes the solution for running Windows software on a computer running macOS?

- A. Operating system spoofing
- B. Remote software provisioning
- C. Indirect software implementation
- D. Cross-platform virtualization

**Answer:** D

**NEW QUESTION 27**

A user, who is attempting to give a presentation via a projector in a conference room, reports the projector has video but no audio. Which of the following will MOST likely resolve the issue?

- A. Changing the input on the projector to VGA
- B. Changing the output on the PC to DVI
- C. Modifying the projector's refresh rate
- D. Utilizing an HDMI connection

**Answer:** D

**NEW QUESTION 28**

Which of the following is the PRIMARY security concern with virtual machine escape?

- A. Cross-site scripting
- B. Compromising the hypervisor
- C. Overutilization of resources
- D. Rogue virtual machines installed on the hypervisor

**Answer:** B

**NEW QUESTION 32**

A customer is using a satellite internet connection that is experiencing slowness. A technician notices high latency while pinging, but the download test is performing perfectly with very good download speeds. Which of the following represents the NEXT action the technician should perform?

- A. Restart the modem and run an online internet connection and speed diagnostic tool.
- B. Guide the customer on how to upgrade the internet plan with the provider in order to improve latency.
- C. Explain to the customer this is not an issue; this situation is normal for this type of internet connection.
- D. Replace the modem because it is not working correctly based on the test result.

**Answer:** A

**NEW QUESTION 33**

A technician is monitoring all outbound traffic in a SOHO. Which of the following is the MOST cost-effective solution to monitor the traffic?

- A. Spectrum analyzer
- B. Network tap

- C. Lookback plug
- D. Toner probe

**Answer: B**

#### **NEW QUESTION 34**

A technician wants to deploy a .msi package to a corporate network. The technician needs to verify the application deployment will not affect other legacy applications on the end users' computers. Which of the following would the technician consider the MOST appropriate for this situation?

- A. Virtual network
- B. Application virtualization
- C. Cross-platform virtualization
- D. Virtual sandbox
- E. Virtual desktop

**Answer: A**

#### **NEW QUESTION 38**

A remote user called the help desk to report a notification indicating there is limited or no connectivity. The user can access local file folders and other local machines but none of the organization's servers or network items. Web pages do not appear to function either. Which of the following is the MOST likely cause of the issue?

- A. The user's internet connection is down.
- B. The user's domain account is locked out.
- C. The user's switch has stopped working.
- D. The user's IP address needs to be renewed.

**Answer: D**

#### **NEW QUESTION 43**

A user brings an older laptop to the help desk and reports issues with the keyboard. Upon inspection, the technician does not see any external damage but notices that many keystrokes do not register in a word processor. The laptop works fine when the technician tests it with an external keyboard. Which of the following actions would MOST likely resolve the issue?

- A. Disable the sticky keys feature.
- B. Clean the keyboard.
- C. Reset the BIOS settings to default.
- D. Charge the laptop.

**Answer: C**

#### **NEW QUESTION 48**

While implementing a non-carrier-grade wireless backhaul, a technician notices the current channel selection is externally polluted with various RF signals. Upon performing a spectral analysis, the technician discovers a channel containing almost no RF pollution. Unfortunately, the technician is unable to select that channel. Which of the following is the MOST likely reason for this issue?

- A. The channel is reserved for licensed band use.
- B. The channel selection is defective, contact the manufacturer.
- C. The channel must be unblocked by the vendor.
- D. The device requires a firmware update to unlock the channel.

**Answer: A**

#### **Explanation:**

The 2.4 GHz band is subdivided into up to 14 channels, spaced at 5 MHz intervals from 2412 MHz up to 2484 MHz. Wi-Fi requires bandwidth of approximately 20 MHz, not 5 MHz. Consequently, a site designer needs to choose the channels that do not overlap. On a WLAN where only the first 11 channels are available, channels 1, 6, and 11 can be selected as non-overlapping. Note: In the Americas, regulations permit the use of channels 1-11 only, while in Europe, channels 1-13 are permitted. In Japan, all 14 channels are permitted.

#### **NEW QUESTION 52**

A computer that contains critical data has not been backed up and will not boot past a S. M. A. R. T. error that indicates imminent hard disk failure. Which of the following actions should the technician take FIRST?

- A. Run diagnostics on the faulty hard drive using a boot disk
- B. immediately replace the hard drive generating the SMART error
- C. Turn off
- D. Turn on, monitoring in the computer's BIOS settings
- E. Attempt to boot the operating system in safe mode

**Answer: B**

#### **NEW QUESTION 53**

An engineer is experiencing unexpected reboots on a graphics workstation when rendering complex 3-D models. The workstation is configured with a 115V power supply that is rated at 200W and connected to a UPS. The central processing unit contains 16 hyperthreaded cores, and a discrete graphics solution utilizing an 8-pin power connector is installed in a PCI Express x16 slot. Which of the following indicates where the technician should begin troubleshooting?

- A. The UPS, as 115V is insufficient for the configuration and should be increased to 220V

- B. The power supply, as 200W is insufficient when the GPU is heavily tasked
- C. The graphics card, as it is the component that triggers the unexpected reboots
- D. The motherboard, as only standard PCI slots should be used for high-end graphics cards, not PCI Express slots

**Answer:** B

**NEW QUESTION 54**

A user is installing a new display on a desktop computer that only has a single DVI port for video input and a single HDMI port for video output. Which of the following does the technician need to complete the setup?

- A. Digital-to-analog converter
- B. A/V switcher
- C. DisplayPort to HDMI adapter
- D. DVI to HDMI cable

**Answer:** D

**Explanation:**

The technician will need to connect the DVI port on the computer to the new display's HDMI port. To do this, a DVI to HDMI cable will be needed. This type of cable will allow the computer's DVI video signal to be transmitted to the new display's HDMI port.

A digital-to-analog converter (DAC) is used to convert a digital signal to an analog signal. An A/V switcher is used to switch between multiple audio and video sources and display them on a single monitor or display. A DisplayPort to HDMI adapter is used to convert a DisplayPort signal to an HDMI signal, but it is not necessary in this scenario as the computer has a DVI port and not a DisplayPort.

**NEW QUESTION 58**

A user is researching hard drives to upgrade a PC and has decided to purchase a NVMe drive. Which of the following should the user confirm are available on the PC before making the purchase? (Select TWO).

- A. SATA
- B. M.2
- C. PCIe
- D. SAS
- E. SCSI
- F. DRAM

**Answer:** BC

**Explanation:**

NVMe (Non-Volatile Memory Express) drives are high-speed solid-state drives that utilize the PCIe (Peripheral Component Interconnect Express) interface to connect to the motherboard. Before purchasing an NVMe drive, the user should confirm that the PC has an available M.2 slot for the drive and that the PC has a PCIe interface for the M.2 slot.

SATA (Serial ATA) is an older interface for hard drives and is not compatible with NVMe drives. SAS (Serial Attached SCSI) is a newer interface for hard drives and is typically used for enterprise-level storage systems.

SCSI (Small Computer System Interface) is a parallel interface for hard drives that is primarily used in high-end workstations and servers. DRAM (Dynamic Random Access Memory) is a type of memory commonly used in computers, but it is not relevant to the storage of data on a hard drive.

**NEW QUESTION 63**

A user submits a help desk ticket regarding a smartphone that will no longer accept its charging cable. The assigned technician notices the phone does not have a protective case, and the user constantly transports the phone in a pocket. The technician attempts to use a secondary charger, but the cable falls out of the phone. Which of the following is the MOST likely cause of the issue?

- A. The phone requires a firmware update to address charging issues.
- B. The charge port contains foreign objects, such as lint.
- C. The phone's battery has swelled, preventing the utilization of the charge port.
- D. The phone has experienced water damage, thus the battery is not charging.

**Answer:** B

**NEW QUESTION 65**

Which of the following describes the main difference between T568A and T568B cabling standards?

- A. The T568B data transfer rate is higher than T568A.
- B. The green and the orange cables are interchanged.
- C. T568A is used in blue cables, and T568B is used in green cables.
- D. The standards use different cable connectors.

**Answer:** A

**NEW QUESTION 66**

Which of the following is a method that can be used to securely connect a remote user's laptop to a corporate server?

- A. WAN
- B. VPN
- C. SSL
- D. DHCP

**Answer:** B

**NEW QUESTION 67**

Which of the following network services allows a networked device to always be assigned the same IP address based on the device's MAC address?

- A. DHCP
- B. LDAP
- C. UTM
- D. DNS

**Answer:** A

**NEW QUESTION 71**

Which of the following cables replaced the Apple 30-pin connector and is also reversible?

- A. USB-C
- B. Lightning
- C. miniUSB
- D. DisplayPort

**Answer:** B

**Explanation:**

Lightning Connector: Apple introduced this brand-new connector back in 2012. It is over 80% smaller than the 30-pin connector and is reversible.  
[https://www.cablewholesale.com/support/technical\\_articles/whats\\_your\\_port.php#:~:text=Lightning%20Connec](https://www.cablewholesale.com/support/technical_articles/whats_your_port.php#:~:text=Lightning%20Connec)

**NEW QUESTION 72**

A technician is setting up a new desktop computer and will be installing the hard drive directly on the motherboard without using cables to connect it. Which of the following will the technician be installing?

- A. Thunderbolt
- B. eSATA
- C. M.2
- D. SCSI

**Answer:** C

**NEW QUESTION 76**

A technician was called in to look at a user's PC. The user reported the PC was very sluggish. The HDD light on the PC was constantly on without blinking. The PC itself was slow receiving input and took a very long time to load the OS. The technician also noticed updates had failed. Which of the following is MOST likely the cause of these issues?

- A. The hard disk drivers have been corrupted
- B. The HDD cables need reseating.
- C. A RAID disk failed.
- D. The HDD has no free space.

**Answer:** A

**NEW QUESTION 79**

A university student was able to boot from a live Linux CD on a computer in a shared space on campus. Which of the following will BEST prevent this type of action from occurring in the future?

- A. Require TPM security features.
- B. Set a boot password.
- C. Disable all media options.
- D. Enable secure boot.

**Answer:** A

**NEW QUESTION 80**

A technician needs to install a cost-effective storage device into a rackmount server that will be used as a VM host. This storage will be used for all VMs that run from the server. Which of the following should be used?

- A. Optical disk drive
- B. eMMC storage device
- C. 15,000rpm drive
- D. RAID 10 array

**Answer:** C

**NEW QUESTION 84**

A technician identified an issue on a workstation, obtained details from the user, and made a backup of the system. Which of the following should the technician do NEXT?

- A. Determine the next steps to resolve the issue and document it.
- B. Design a plan of action to resolve the issue and implement the solution.
- C. Document the findings, actions, and outcomes.

D. Establish a theory of probable cause, researching internally or externally as needed.

**Answer:** D

**Explanation:**

"Identify the problem. • Question user and identify user changes to computer. • Perform backups before making changes. • Inquire regarding environmental or infrastructure changes. • Review system and application logs. \* 2. Establish a theory of probable cause (question the obvious and if necessary, conduct internal or external research based on symptoms)

**NEW QUESTION 86**

A help desk technician has been tasked with installing an IP phone in a small office with an unmanaged switch. When connected to an RJ45 receptacle, the phone does not boot. Which of the following is the QUICKEST way to resolve this issue?

- A. Upgrade the Ethernet cable to the latest specification.
- B. Replace the phone.
- C. Install a PoE injector.
- D. Change ports on the switch.

**Answer:** C

**Explanation:**

<https://intellinetnetwork.eu/pages/what-is-a-poe-injector>

**NEW QUESTION 87**

An organization is looking to upgrade the processing ability for its computers. Most users report that whenever multiple applications are being utilized, the system's response time slows down drastically. When only one application is open, the response time is acceptable. Which of the following should be upgraded FIRST?

- A. SSD
- B. CPU
- C. HDD
- D. RAM

**Answer:** D

**Explanation:**

'Upgrading to a faster CPU will improve your PC's single-application performance, making games run more smoothly, for example. Adding more RAM to your PC increases its multitasking capacity, but won't necessarily improve its single-application performance'

**NEW QUESTION 89**

A technician needs to install a printer on the network. Which of the following must the technician configure? (Select THREE).

- A. PCL
- B. Dots per inch
- C. Gateway
- D. Subnet mask
- E. MAC address
- F. MB
- G. IP address
- H. Drivers

**Answer:** AEH

**NEW QUESTION 91**

An online retailer wants to save money and is considering migrating to the public cloud so peak is over. Which of the following BEST describes this aspect of cloud computing?

- A. Rapid elasticity
- B. Metered utilization
- C. Shared resources
- D. High availability

**Answer:** A

**Explanation:**

Rapid elasticity is only suitable for a domain whose resource requirements suddenly up and down for a specific time interval. Referring to the question the online retailer wants to migrate to public cloud services during peak season, then wants it to be removed "automatically" when the peak is over.

**NEW QUESTION 92**

An IT manager discovered that hundreds of pages of printed materials are being recycled each day because the materials are left on the printer tray instead of being picked up by users. Which of the following would BEST prevent this waste?

- A. Send friendly reminders to not print unnecessarily.
- B. Enable duplex printing to reduce paper utilization.
- C. Bill each department for the excess material cost.
- D. Require a code or badge before releasing a print job.

**Answer:** B

**NEW QUESTION 95**

A user is unable to access the internet on a PC. A technician examines the PC and runs the following commands:

```
ipconfig /all
ping 8.8.8.8
ping comptia.org
```

Which of the following steps in the troubleshooting process does this series of commands represent?

- A. Establish a theory.
- B. Verify full system functionality.
- C. Establish a plan of action.
- D. Identify the problem.

**Answer: B**

**NEW QUESTION 98**

Which of the following is the SAFEST way to replace RAM on a server that has a redundant power supply?

- A. Unplug one power cable.
- B. Verify the RAM temperature.
- C. Utilize a grounding strap.
- D. Replace the RAM while the server is running.

**Answer: C**

**Explanation:**

Utilizing a grounding strap is the safest way to replace RAM on a server that has a redundant power supply. This ensures that no static electricity is transferred to any of the server components, which could cause permanent damage. The other options are not the correct methods for replacing RAM. Unplugging one power cable is not recommended, as it could cause the server to go offline and disrupt any services that are running. Verifying the RAM temperature is not necessary and does not provide any additional safety measures, and replacing the RAM while the server is running is not recommended, as it could cause system instability.

**NEW QUESTION 100**

A technician is adding one more line at the demarcation point. Which of the following tools would be MOST useful to accomplish this task?

- A. Toner
- B. Punchdown
- C. Network tap
- D. Crimper

**Answer: B**

**Explanation:**

Punchdown tools are used to make connections between wires in a 66/110 block at the demarcation point. The tool is used to insert the wire into the appropriate holes in the block, and it can be used to add additional lines to the demarcation point. The other options are not the correct tools for adding lines to the demarcation point. A toner is used to identify cable pairs, a network tap is used to monitor network traffic, and a crimper is used to terminate cables.

**NEW QUESTION 105**

A company wants to use client-side visualization for application testing. Which of the following configurations would BEST support this goal?

- A)  
CPU 2.5GHz - 4 cores  
16GB DDR4 RAM  
1TB SSD
- B)  
CPU 3.2GHz - 1 core  
16GB DDR4 RAM  
4TB SSD
- C)  
CPU 2.5GHz - 2 cores  
16GB DDR4 RAM  
4x 1TB HDD RAID 5
- D)  
CPU 3.2GHz - 4 cores  
8GB DDR4 RAM  
500GB HDD

- A. Option A
- B. Option B
- C. Option C
- D. Option D

**Answer: A**

**NEW QUESTION 106**

A technician installs a new printer for a workstation and tries to print a test page, but the page does not print. The technician looks at the print queue and notices that the printer is called 'Generic Printer.' Which of the following BEST describes what the technician should do to fix this issue?

- A. Connect the printer with a USB cable rather than over the network.
- B. Install the appropriate printer drivers for the OS.
- C. Install the correct toner in the printer.
- D. Set the printer trays to allow duplex printing

**Answer: B**

**NEW QUESTION 111**

A technician is diagnosing a workstation that shuts down unexpectedly during a butn-in test. Which of the following is the MOST likely cause for this symptom?

- A. Faulty CMOS battery
- B. OS update issue
- C. Overheating
- D. Faulty RAM

**Answer: C**

**NEW QUESTION 116**

A technician is configuring a new CAD workstation that has four large hard drives. The workstation will be used to edit large, critical files, so the storage configuration should be both fast and redundant. Which of the following RAID levels BEST meets these requirements?

- A. 1
- B. 5
- C. 10

**Answer: D**

**Explanation:**

<https://techgenix.com/raid-10-vs-raid-5/>

**NEW QUESTION 121**

A technician is preparing to set up a gaming computer with the following components:

- Discrete, high-end graphics card
- Video capture card
- High-end processor
- Multiple hard drives
- USB 3.0 hub
- Sound card

Which of the following options is the MOST important for the technician to consider before building the gaming computer?

- A. Redundant power supply
- B. Modular power supply
- C. 20-pin v
- D. 24-pin power adapter
- E. Power supply wattage rating

**Answer: D**

**NEW QUESTION 122**

A user is unable to plug a USB 3.0 device into a USB port. Upon inspection, a technician notices the USB 3.0 port appears to be slightly smaller than the other connections. Which of the following is the MOST likely cause?

- A. A foreign object is stuck inside the port
- B. The cable connection utilized the wrong orientation.
- C. The USB cable is physically damaged.
- D. The USB port belongs to a different form factor.

**Answer: D**

**Explanation:**

USB 3.0 ports are slightly smaller than other USB connections, so if the port appears to be the wrong size, it is likely that the port belongs to a different form factor. This can be caused by a number of factors, such as the device being too old to support USB 3.0, or the device not having a USB 3.0 port in the first place.

**NEW QUESTION 126**

A user on a SOHO network is unable to watch online videos, even at 240 pixels. The technician runs ipconfig from the user's computer and records the following:

```
Connection-specific DNS Suffix .: lan
Link-local IPv6 Address . . . . .: fe80::1585:7fb2:b05f:7102%12
IPv4 Address. . . . .: 192.168.1.131
Subnet Mask . . . . .: 255.255.255.0
Default Gateway . . . . .: 192.168.1.1
```

The technician then connects a test laptop to the router via the user's Cat 5 cable and records the following information:

```
Download: 85 mbps
Upload: 22 mbps
Ping: 28 ms
```

Which of the following is MOST likely causing the user's issue?

- A. Incorrect IP address
- B. Faulty NIC
- C. Misconfigured default gateway
- D. Bad network cable

**Answer: B**

**NEW QUESTION 131**

A technician is setting up a device to use two-factor authentication. Which of the following meets this requirement?

- A. Thumbprint/retinal scan
- B. Password/password
- C. Password/thumbprint
- D. Password/PIN

**Answer: C**

**NEW QUESTION 133**

A technician is inspecting a projector that is displaying fuzzy images. Which of the following actions would provide the BEST solution?

- A. Adjusting the lens
- B. Changing the filter
- C. Replacing the video cable
- D. Reseating the lamp

**Answer: A**

**NEW QUESTION 137**

Which of the following components enables the input on a mobile device's touch screen?

- A. OLED
- B. Digitizer
- C. Inverter
- D. CMOS sensor

**Answer: B**

**NEW QUESTION 142**

To control costs a company provides a limited number of users with company phones. One of these users opens a support ticket because the phone no longer allows internet browsing over a cellular connection. The user acknowledges that the phone worked before the user's child streamed several movies using the device. Which of the following describes why the phone cannot browse the Internet?

- A. The child accidentally connected to a neighbor's WLAN
- B. The company's group policy disabled the device
- C. The device has a data cap and has reached that limit
- D. The device's plan has been unpaid

**Answer: C**

**Explanation:**

It is common for companies to place a data cap on the devices they provide to their employees, to control costs. If a user has exceeded the data cap, the phone may no longer allow internet browsing over a cellular connection. This is usually because the cellular data usage has exceeded the allotted amount for the particular plan the device is on, and the service provider has temporarily suspended the data connection.

It is unlikely that the child accidentally connected to a neighbor's WLAN because this would not affect the cellular data connection. Similarly, it is unlikely that the company's group policy has disabled the device, as this would likely affect all devices under the same policy. If the device's plan has been unpaid, the service provider would likely temporarily suspend all services, not just the cellular data connection.

**NEW QUESTION 147**

A company just bought a printer capable of automatically printing on both sides of the paper. After installation, however, the technician can only print on both sides of the paper manually. Which of the following should the technician do to fix the issue?

- A. Install the most recent firmware upgrade available for the printer.
- B. Contact the vendor for a hardware replacement.

- C. Reinstall the printer software and drivers, and then restart the printer.
- D. Read the installation manual and configure duplex settings.

**Answer:** D

**NEW QUESTION 148**

Which of the following allows a switch to be divided into separate logical networks?

- A. VLAN
- B. SSL VPN
- C. NAT
- D. RADIUS

**Answer:** A

**Explanation:**

A Virtual LAN (VLAN) is a network topology that allows a switch to be divided into separate logical networks. This allows for the creation of multiple broadcast domains within a single physical network, improving network segmentation and security. With VLANs, you can segment your network so that different departments, applications, or users are isolated from each other, improving network security and performance.

**NEW QUESTION 151**

A startup company is outgrowing its current office space and is requiring employees to work remotely. The company must comply with government-enforced requirements to safeguard all aspects of data, so the IT department plans to maintain complete control over users' operating systems. Which of the following should the IT department implement?

- A. VDI
- B. IaaS
- C. VPN
- D. SaaS

**Answer:** A

**NEW QUESTION 154**

A new employee has been issued a company laptop. The employee requests an accessory with a single power source that has wired network connectivity and supports a keyboard, mouse, speakers, and dual monitors. Which of the following accessories should the systems administrator deploy to BEST meet the new user's needs?

- A. PoE switch
- B. USB-C hub with power delivery
- C. Docking station with DisplayPort
- D. KVM switch with audio

**Answer:** C

**NEW QUESTION 157**

A user on the marketing team uses various multimedia applications that consume a lot of memory. The user needs to install more RAM to run these applications effectively. When the user opens the computer case, the user sees four slots in two sets of colors. Which of the following memory types is MOST likely required?

- A. Dual-channel
- B. Triple-channel
- C. Single-channel
- D. Quad-channel
- E. Error correction code RAM

**Answer:** A

**NEW QUESTION 162**

A user requested upgrades to a company-issued laptop to increase its performance while working with a large database stored on drive C. Which of the following tasks should a systems administrator complete to BEST meet this goal? (Select TWO).

- A. Configure RAID 1.
- B. Install a hybrid drive.
- C. Upgrade to 1GB NIC.
- D. Increase the RAM.
- E. Migrate to a SSD.
- F. Upgrade the power supply.

**Answer:** BD

**Explanation:**

CompTIA covers it in page 97 of the comptia A+ complete study guide.

**NEW QUESTION 164**

A technician has set up a new conference room with a TV and a video soundbar. The technician wants to test the system with a conference call. During the test, the TV speaker produces sound, but the soundbar does not. Which of the following is the MOST likely cause of the issue?

- A. The volume on the TV needs to be turned up.
- B. The conference call needs to be unmuted for audio.
- C. An incorrect HDMI cable is being used.
- D. The TV's HDMI-ARC port is not being use

**Answer:** D

**Explanation:**

HDMI-ARC (Audio Return Channel) is an HDMI connection that allows audio to be sent from the TV to an external sound system, such as a soundbar. If the TV's HDMI-ARC port is not being used, then the soundbar will not receive any audio from the TV and thus will not produce any sound. To resolve the issue, the technician should ensure that the TV's HDMI-ARC port is being used to connect the TV to the soundbar.

**NEW QUESTION 165**

A user creates a support ticket to report a conference room projector that does not work. The user says that even though the provided cables are being used, the projector screen shows the following error message:

No signal input

Which of the following describes the FIRST action that should be taken?

- A. Verify that the projector is turned on.
- B. Verify that the user is using an approved OS.
- C. Replace the projector bulb.
- D. Check the video cable and replace it if necessary.

**Answer:** D

**Explanation:**

The most common reasons you may be seeing the "No Signal" message: The projector and the source device are not connected correctly.

**NEW QUESTION 168**

A technician receives several error alerts on a server after an unexpected reboot. A message states that one or more disks are in a degraded state. When the technician advances to the next error message, it indicates the OS is missing. Which of the following are the MOST likely causes of these errors? (Choose two.)

- A. Missing drives in the OS
- B. RAID failure
- C. Bootable device not found
- D. Data loss
- E. Controller failure
- F. CMOS corruption
- G. TPM malfunction

**Answer:** BC

**NEW QUESTION 170**

A user connects a smartphone to a laptop. Which of the following types of networks has the user created?

- A. PAN
- B. MAN
- C. WLAN
- D. LAN

**Answer:** A

**NEW QUESTION 174**

Which of the following 802.11 standards supports both 5GHz and 2.4GHz channel frequencies?

- A. 802.11a
- B. 802.11c
- C. 802.11b
- D. 802.11g

**Answer:** B

**NEW QUESTION 178**

A user contacts the help desk in reference to a failing thumbprint scanner. The user states the scanner was functioning correctly yesterday. Which of the following troubleshooting steps should be performed FIRST after the ticket has been filed?

- A. Inquire about possible changes.
- B. File a damage report.
- C. Requisition a new scanner.
- D. Attempt to clean the scanner.

**Answer:** A

**Explanation:**

<http://www.221021.com/Hardware/input-output-devices/32310.html>

\* 1. Identify the problem.

Gather information from the user, identify user changes, and, if applicable, perform backups before making changes.

Inquire regarding environmental or infrastructure changes.

\* 2. Establish a theory of probable cause (question the obvious).

If necessary, conduct external or internal research based on symptoms.

\* 3. Test the theory to determine the cause.

Once the theory is confirmed, determine the next steps to resolve the problem. If the theory is not confirmed, re-establish a new theory or escalate.

\* 4. Establish a plan of action to resolve the problem and implement the solution. Refer to the vendor's instructions for guidance.

\* 5. Verify full system functionality and, if applicable, implement preventive measures.

\* 6. Document the findings, actions, and outcomes.

#### NEW QUESTION 182

A user that works in sales is reporting that the output on each page printed from a laser has duplicate images. Which of the following should be performed FIRST to eliminate the ghost images?

- A. Change the paper weight setting.
- B. Replace the printer's fuser.
- C. Upgrade the printer firmware.
- D. Clean the toner drums and rollers

**Answer: C**

#### NEW QUESTION 184

A user in a medical office contacts a technician regarding a printer that is used to print A4-sized labels. After the labels are printed, they mistakenly contain white space in the middle of the page. Which of the following would MOST likely be the cause?

- A. Contaminated fuser
- B. Worn rollers
- C. A misfeed
- D. Page orientation

**Answer: A**

#### Explanation:

The most common symptoms that indicate fuser deterioration are: The print leaves parallel spots across a sheet. The printer begins to loosen toner and does not stick to the sheet. Stains on printed sheets. Annoying noise from gear wear. The fusers are the core in the printing process of a laser printer. The Fuser is the piece that fixes the toner on the paper.

#### NEW QUESTION 189

A user reports that printed receipts have black smudges over the entire image. The text is still present but is very dark and sometimes illegible. Which of the following are the MOST likely cause and solution for the printer issue?

- A. The ribbon is jammed and is rubbing on the paper
- B. Clear the bad ribbon and feed it through properly.
- C. The printhead is too hot
- D. Adjust the temperature down and retry printing.
- E. The printer is loaded with the wrong type of paper
- F. Replace the receipt paper with carbon paper.
- G. The blue ink cartridge was loaded with black ink
- H. Put in the correct ink and clean the printhead.

**Answer: B**

#### Explanation:

Receipts are printed via a thermal printer. Thermal printers work by heating a paper in specified areas in order to create an image. The specific component that does this is a thermal printhead. Since the image appears to have black smudges and is too dark, we know the thermal printhead is too hot since the capability of precise heating has diminished.

#### NEW QUESTION 194

A company needs to support a 10Gbps throughput. Which of the following is the MINIMUM cable category that could be used?

- A. Cat 5
- B. Cat 5e
- C. Cat 6
- D. Cat 6a

**Answer: C**

#### NEW QUESTION 196

Client-side virtualization guest machines have security requirements similar to physical machines, but they also need to ensure separation from other guest machines. Which of the following BEST describes this client-side guest security requirement?

- A. Isolation
- B. Authentication
- C. Hardening
- D. Authorization

**Answer: A**

**NEW QUESTION 197**

A user working in the field reported the GPS stopped working on a phone. The user's older, in-car GPS continued to function. Later, the user reported that the phone's GPS started working again. Which of the following MOST likely caused the phone's GPS to fail?

- A. The cell phone was in conservation mode
- B. The cell phone had lost service to the earner
- C. The eel phone received a firmware update
- D. The cell phone had overheated

**Answer:** A

**NEW QUESTION 198**

A technician set up a new access point and has noticed significant latency on the selected channel. Which of the following tools can assist with locating the BEST channel to use?

- A. Wi-Fi analyzer
- B. Netstat
- C. Net use
- D. Traceroute
- E. Network tap

**Answer:** A

**Explanation:**

A Wi-Fi analyzer is a tool that can be used to scan the local area for available wireless networks and can provide information such as signal strength, interference, and available channels. It can also be used to locate the best channel to use for a given access point, which can help to reduce latency and improve performance.

**NEW QUESTION 202**

A home user has purchased a subscription for a service that blocks malicious sites by preventing them from resolving correctly. Which of the following settings MOST likely needs to be changed on the user's router to enable this functionality?

- A. DNS server
- B. Port forwarding
- C. Perimeter network
- D. Universal PnP
- E. DHCP server

**Answer:** A

**NEW QUESTION 206**

A technician is tasked with upgrading a laptop's RAM. Which of the following steps should the technician take FIRST?

- A. Confirm that both the current and new memory are from the same brand.
- B. Run a diagnostic test on the current memory.
- C. Verify the memory requirements of the motherboard.
- D. Connect an electrostatic discharge strap.

**Answer:** D

**NEW QUESTION 207**

A user calls the help desk lot assistance configuring an Android phone with a new NFC-enabled speaker that will be used for an upcoming conference call. The user was unable to direct the phone's audio to the NFC speaker. Which of the following sequences should the help desk technician walk the customer through to accomplish this task?

- A. Enable NFC on the speake
- B. Ensure the speaker is less than 33ft (10m) from the Android phon
- C. On the phone's Bluetooth settings menu for Connected Devices, select Pair New Devic
- D. Tap to accept the connection to the speaker when the prompt is displayed on the phone's screen.
- E. Enable NFC and Bluetooth on the Android phon
- F. From the Android phone's Bluetooth settings menu for Connected Devices, select the Previously Connected Devices optio
- G. Select a listed device that most closely matches the speake
- H. Tap lo accept the connection lo the speaker when the prompt is displayed on the phone's screen.
- I. Enable NFC and Bluetooth on the Android phon
- J. Tap and hold the Android phone to the spot on the speaker where the NFC logo is displaye
- K. Accept the connection to the speaker when the prompt is displayed on the phone's screen.
- L. Enable Wi-Fi on the speake
- M. Enable Wi-Fi on the Android phon
- N. Tap and hold the Android phone to the spot on the speaker where the NFC logo is displaye
- O. Accept the connection to the speaker when the prompt is displayed on the phone's screen.

**Answer:** A

**NEW QUESTION 211**

Which of the following would be BEST reason to use a virtual machine as a sandbox?

- A. To test new software in a safe environment
- B. To increase the efficient use of computing resources
- C. To run multiple machines on the same hardware

D. To have dedicated hardware for a single system

**Answer:** A

**NEW QUESTION 216**

A technician is troubleshooting a projector that will not display any images. The technician has verified the computer output and cable are providing a good video signal. Which of the following should the technician do NEXT?

- A. Calibrate the image.
- B. Replace the bulb.
- C. Test the output resolution.
- D. Clean the fans.

**Answer:** A

**NEW QUESTION 219**

A network administrator was notified that laptop users are unable to access or ping any network resources on the corporate network. Which of the following should the network administrator check FIRST?

- A. DHCP
- B. AAA
- C. DHB
- D. ARP

**Answer:** A

**Explanation:**

Domain Name System (DNS) is an Internet service that translates domain names (e.g., its.umich.edu) into IP addresses. Dynamic Host Configuration Protocol (DHCP) is a protocol for automatically assigning IP addresses and other configurations to devices when they connect to a network.

**NEW QUESTION 221**

Which of the following cloud models maintains access, even when a local internet outage occurs?

- A. Private
- B. SaaS
- C. Community
- D. Public

**Answer:** A

**Explanation:**

In a private cloud model, the cloud infrastructure is maintained within a company's own data center and is used exclusively by that company. Private clouds offer the advantage of maintaining access even when a local internet outage occurs, since the cloud infrastructure is not dependent on a public network connection. Software as a Service (SaaS) is a cloud model in which software applications are hosted by a third-party provider and made available to customers over the internet. SaaS is not designed to maintain access in the event of a local internet outage.

A community cloud is a shared infrastructure that is used by multiple organizations, typically from the same industry or with similar requirements. Community clouds are not designed to maintain access in the event of a local internet outage.

A public cloud is a cloud infrastructure that is maintained by a third-party provider and is made available to the public over the internet. Public clouds are not designed to maintain access in the event of a local internet outage.

**NEW QUESTION 222**

A user reports limited or no connectivity on a laptop. A technician runs `ipconfig /all` with the following result:

```
IPv4 connectivity...limited or none
IPv4 address...169.254.254.1
subnet mask...255.255.0.0
default gateway...
```

Which of the following is the MOST likely cause of this issue?

- A. DHCP failure
- B. ARP cache
- C. DNS resolution
- D. Duplicate IP address

**Answer:** A

**NEW QUESTION 227**

A field technician has been dispatched to a site with an internet outage. Upon arriving, the technician discovers that the POTS lines are not working as well. Which of the following technologies is the site MOST likely using?

- A. Fiber
- B. Cable
- C. DSL
- D. Satellite

**Answer:** C

**NEW QUESTION 229**

A user's laptop is running out of disk space and requires a new hard drive. The user wants to replace the existing hard drive with the fastest possible 1 TB HDD. A technician assesses the user's hardware and determines the connections that are available. Which of the following drive types should the technician recommend as the BEST choice?

- A. 1TB NVMe SSD
- B. 1TB flash drive
- C. 1TB SATA SSD
- D. 1TB SAS

**Answer:** A

**Explanation:**

The best choice for the user's laptop is a 1TB NVMe SSD. NVMe (Non-Volatile Memory Express) is a high-performance storage protocol designed specifically for solid-state drives (SSDs). It is significantly faster than SATA SSDs and SAS hard drives, making it ideal for users who need fast storage for their laptop. NVMe SSDs also have lower latency and higher bandwidth than traditional hard drives, making them well-suited for data-intensive tasks such as video editing, gaming, and running multiple applications simultaneously. Additionally, NVMe offers more reliable data reliability than traditional hard drives, and is less susceptible to performance degradation over time.

**NEW QUESTION 232**

A customer reports that a computer is never able to reach more than a 100Mbps transfer data rate, even when using a Gigabit LAN card. While troubleshooting, the technician notices the network cable needs to be replaced. Which of the following cable categories is limiting the transfer speed?

- A. Cat 5
- B. Cat 5e
- C. Cat 6
- D. Cat 6a

**Answer:** A

**NEW QUESTION 236**

A technician is troubleshooting a smartphone that has a large dark area on the screen. The screen has no damage to indicate that it is cracked. Which of the following BEST describes why a blot is on the screen?

- A. Digitizer damage
- B. Improper charging
- C. Ambient light sensor damage
- D. Liquid damage

**Answer:** A

**Explanation:**

A blot on the screen of a smartphone is most likely caused by damage to the digitizer, which is the part of the device responsible for interpreting touch input. Improper charging is unlikely to cause a blot on the screen, as is damage to the ambient light sensor. Liquid damage is a possibility, but it is more likely to cause discoloration or other physical damage to the screen.

**NEW QUESTION 238**

A technician is upgrading a legacy wireless router for a home user. After installing the new router and configuring the SSID to be the same, none of the devices will connect to the network. Which of the following should the technician check NEXT?

- A. DHCP pool configuration
- B. MAC filtering list
- C. Wireless protocol settings
- D. DNS servers

**Answer:** B

**NEW QUESTION 242**

A laptop has been returned for a screen repair. The owner insists the screen is broken, but occasionally a faded image is able to be seen in very bright settings on the desktop. Which of the following steps should the repair technician take FIRST?

- A. Replace the graphics card.
- B. Replace the screen, as the customer insists.
- C. Recommend the usage of an external display instead.
- D. Ensure the backlight is functioning as expected.

**Answer:** D

**NEW QUESTION 244**

While using a popular videoconferencing program, the user selects a webcam, but the software is unable to open the webcam. The webcam was working the previous day. Which of the following should be done to address this issue?

- A. Close other video software and retry.
- B. Adjust the conference software to a compatible resolution.
- C. Switch the video from the webcam to "conference" mode.
- D. Reseat or replace the webcam.

**Answer:** A

**Explanation:**

Web cameras can input to one software at a time. Closing other video software is the first step in troubleshooting the issue as it doesn't require customer or on-site support. After restarting the computer and adjusting the drivers, it would be time to ask the customer to reseat the webcam or replace the device.

**NEW QUESTION 248**

A user's mobile phone gets really hot to the touch and does not retain a charge. The user also reports that the phone is very slow, especially while charging. Which of the following is MOST likely causing these symptoms?

- A. Broken charging port
- B. Digitizer failure
- C. CPU overheating
- D. Defective battery

**Answer:** D

**NEW QUESTION 252**

Which of the following is the MAXIMUM power PoE+ provides?

- A. 15.4W
- B. 30W
- C. 60W
- D. 95W

**Answer:** B

**Explanation:**

The earliest PoE switches from a few years ago generated 15 Watts per port (IEEE 802.3af). Today, most use the PoE+ standard (IEEE 802.3at), which generates up to 30 Watts per port. That's plenty for most devices that people want to connect

**NEW QUESTION 253**

While implementing a non-carrier-grade wireless backhaul, a technician notices the current channel selection is extremely polluted with various RF signals. Upon performing a spectral analysis, the technician discovers a channel containing almost no RF pollution. Unfortunately, the technician is unable to select that channel. Which of the following is the MOST likely reason for this issue?

- A. The channel is reserved for licensed band use.
- B. The channel selection is defective; contact the manufacturer.
- C. The channel must be unlocked by the vendor.
- D. The device requires a firmware update to unlock the channel.

**Answer:** D

**NEW QUESTION 258**

.....

## Thank You for Trying Our Product

\* 100% Pass or Money Back

All our products come with a 90-day Money Back Guarantee.

\* One year free update

You can enjoy free update one year. 24x7 online support.

\* Trusted by Millions

We currently serve more than 30,000,000 customers.

\* Shop Securely

All transactions are protected by VeriSign!

**100% Pass Your 220-1101 Exam with Our Prep Materials Via below:**

<https://www.certleader.com/220-1101-dumps.html>